

# Beef Cattle Barn

Herrick Archives Building 005

## A. IDENTIFICATION & LOCATION

### 1. Name

1. 1 Never officially named by Board of Trustees action.


1. 2 Alternate names noted:

Beef Cattle Building

### 2. Location

2.1 Located at 2027 Plumb Hall Court. See map below.

2.2 For greater detail, see Sheets 67 and 80 in the book of campus maps in the University Archives.



For identification of other buildings shown, see Appendix A.

### 3. General Description

3. 1 Type of construction:

Frame interior and wood siding.

3. 2 No. of stories:

One.

3.3 Increments of construction:

No additions noted.

3.4 Present area of building as shown in inventory records of Division of Campus Planning:

15,210 sq. ft. gross; 14, 362 sq. ft. net assignable

3.5 Volume of Building:

317,316 cu. ft. (PP).

## B. PLANNING & CONSTRUCTION

1. On February 17, 1922 the Board of Trustees approved the plans and related documents prepared by Joseph N. Bradford and authorized the solicitation of bids by contractors.
2. Bids were received on March 27, 1922. (T)
3. On April 5, 1922 the Board of Trustees awarded contracts to the following contractors:

General: A. K. McCall & Co.

Electrical: E. H. Cobb

Plumbing: A. K. McCall & Co.

4. Completion and occupancy:

4.1 Building was accepted from contractors on October 20, 1922.

4.2 McCracken lists the building as completed in 1923 (McC 4: 9A). It is possible that some work had to be done after completion of work of the contractors before the building was ready for use.

## C. COST

Listed at \$27,236.53 (B & McC 4: 9A).

## D. DEMOLITION

The Board of Trustees on February 4, 1972 approved demolition of the building.

## E. PHOTOGRAPHS

1. In Photoarchives:

X 1507--view from northeast

X 1244--view from northeast, Building 005 is the third one from the left.

2. Other:

McC 4: 254

McC 4: 256 (third building from left)

John H. Herrick  
August 24, 1972

## ADDENDUM NO. 1

### Demolition

Demolition began in late November 1972 (L 11/29/72) and was substantially completed by December 5.

However, rubble had not been completely removed by the latter date.

John H. Herrick  
January 16, 1973